



**Richard Jackson**  
Engineering Consultants

## DOLPHINS – VISUAL STRUCTURAL INSPECTION

Brightlingsea Harbour

Brightlingsea Town Council

April 2021

Project no: 61257

**Document Review Sheet: -**

Document prepared by: - *John Wankowski IEng MIED*  
on behalf of Richard Jackson Ltd

Date: - ..01.. / ..04.. / 2021

Document checked by: - *Michael Sturdivant BEng (Hons) FGS AMRINA*  
on behalf of Richard Jackson Ltd

Date: - ..08.. / ..04.. / 2021

Document Approved by: - *Richard Laycock BEng (Hons) CEng MICE*  
on behalf of Richard Jackson Ltd

Date: - ..08.. / ..04.. / 2021

Document Status

DRAFT

FINAL

Revision Status

Issue	Date	Description	Prepared	Checked	Approved

This document has been prepared for the sole use of **Brightlingsea Town Council**, is copyright and its contents should not be relied upon by others without the written authority of Richard Jackson Ltd. If any unauthorised third party makes use of this report they do so at their own risk and Richard Jackson Ltd owe them no duty of care or skill.

All information provided by others is taken in good faith as being accurate, but Richard Jackson Ltd cannot, and does not, accept any liability for the detailed accuracy, errors or omissions in such information.

## Contents:-

<b>1. Introduction.....</b>	<b>2</b>
<b>2. Limitations.....</b>	<b>2</b>
<b>3. Structure.....</b>	<b>2</b>
<b>4. Condition .....</b>	<b>3</b>
<b>5. Discussion.....</b>	<b>4</b>
<b>6. Conclusion .....</b>	<b>4</b>

### **Appendix A**

Photographs

### **Appendix B**

Correspondence with Brightlingsea Museum - Photos reproduced with kind permission

### **Appendix C**

61257 – SK01: Sketch of Brightlingsea Dolphins

## **1. Introduction**

- 1.1. We received written instructions from Brightlingsea Town Council on 29 March 2021 to make a structural inspection of the 3no. mooring Dolphins located in the Brightlingsea Harbour. This was made on 1<sup>st</sup> April 2021.
- 1.2. The subject of the inspection was an assessment of the general structural condition of the 3 No. individual Dolphins.
- 1.3. This Report gives the results of our inspection, discusses these results and gives any recommendations for further action.
- 1.4. The Dolphins are historic harbour mooring structures, anecdotally erected during World War II for military use, somewhere between 1940 & 1942.
- 1.5. It is understood that they were last commercially used during the 1960s and have since then fallen into disuse.
- 1.6. Anecdotally, there has been no scheduled or recorded maintenance of any of the Dolphin structures within the last 40 years.

## **2. Limitations**

- 2.1. A structural inspection is an enquiry into the structural condition of the item at the point of inspection. It is a specialist survey, concerned only with structural matters and not with wider, non-structural matters.
- 2.2. This report has been prepared for the benefit of Brightlingsea Town Council
- 2.3. We are obliged to state that we have not inspected foundations or other parts of the structure which are covered, unexposed or inaccessible and we are therefore unable to say that any such part of the Dolphins are free from defect.

## **3. Structure**

- 3.1. With reference to the hand sketch in Appendix C, the following observations are made.
- 3.2. There are 3 No. structures, their heights vary to match the slope of the harbour tidal flat and keep the top of the structures level. In this report all measurements on each structure is relative to the local ground level of the mud. For clarity the Dolphin closest to the shore is referred to as No. 1 (2.8m tall), and the tallest furthest from the shore is referred to as No. 3. (4.2m tall).
- 3.3. The Dolphins are formed from trussed steel Equal Angle (EA) and Parallel Flange Channel (PFC) members.

- 3.4. Below the high tide line, the main vertical corner members were measured to be approximately 6" x 6" EA (152mm x 152mm) with a section thickness of 12.5mm (following the removal of marine growth and corrosion).
- 3.5. The diagonal bracing members were 3.5" x 3.5" EA (89mm x 89mm), with a section thickness of 9mm (following removal of the marine growth and corrosion).
- 3.6. The horizontal members were 5.5" x 2.5" PFC (140mm x 64mm) (following removal of the marine growth and corrosion).
- 3.7. The plated joints are a mixture of riveted and bolted connections (where possible to differentiate). The measured thickness of the plate at the mud line on No.3 Dolphin was 12mm.
- 3.8. On the northern side the Dolphins have hardwood timber members bolted to the face of the structures to form rubbing plates nominally 6" x 4" (152mm x 102mm).
- 3.9. The Dolphins are designed to have a vertical face on the northern side to accept vessels. The other faces are sloped for structural efficiency.
- 3.10. At the point of inspection the tide was out completely exposing the mud surrounding No.3.
- 3.11. The foundations were not visible.

#### **4. Condition**

- 4.1. The lower sections of the Dolphins were heavily encrusted with marine growth (barnacles & oysters).
- 4.2. At an approximate height of 1.3m above the tidal flat on Dolphin No. 3, seaweed indicated the high tide line. Above this point marine growth was limited or not present. Dolphins No. 2 & 1 exhibited marine growth to similar relative level to the tide line height as No. 3. It should be noted that the majority of No. 1 is above the approximate high tide line.
- 4.3. On all 3 No. moorings, above the high tide line, the steel members were heavily corroded. Some individual members had completely dissolved and others exhibited large holes.
- 4.4. Hammer testing was undertaken upon various members. Below the high tide line following removal of the marine growth the steel was preserved. The marine growth of barnacles particularly on No. 3 was very thick and uniform and had in places completely encased the members below the high tide line (an approximate height of 1.3m).
- 4.5. Above the tide line all members examined had no sectional thickness remaining; striking with a 500g hammer resulted in complete local disintegration of the member.

- 4.6. Without accurate record drawings it is not possible to be certain about the original section thicknesses. From historic literature it may be possible to estimate the original member thickness and calculate the loss of structural capacity.
- 4.7. It was noted with the use of a plumb-bob that No. 3 is not vertical and leans outwards to the north, resulting in the top being >50mm beyond the toe at the mud line. It was not possible to work out if the cant is caused by localised damage to the members below the mud-line or symptomatic of failure of the foundation.

## **5. Discussion**

- 5.1. The corrosion of the steel members above the high tide line is such that, the rust and hardwood rubbing timbers are holding the Dolphins together. These structures are in a dangerous condition, and the Council as their owners are liable for the risks that they present under the Buildings Act 1984.
- 5.2. It would be highly unlikely that any marine insurer would accept the liability of the Dolphins as mooring points in their current condition.

The current structural condition of Dolphins presents a risk of serious injury to individuals if they were to climb or interact with them.

- 5.3. The deterioration of the structures is so widespread that repair is unlikely to be feasible. The structure would have to be completely removed and replaced from just above the mud-Without inspection or testing of the foundation it is not possible to comment upon the condition. If new structure was mounted upon the existing foundation it would be at risk of failure. It is recommended that they be treated as suspect.

## **6. Conclusion**

- 6.1 Given that repair is unfeasible, the only credible option is complete removal of the dolphins to well below the mud-line, to ensure any persons or boats would not be at risk of injury or damage due to the remaining vertical members.

**Appendix A**

Photographs

**Appendix B**

Correspondence with Brightlingsea Museum - Photos reproduced with kind permission

**Appendix C**

61257 – SK01: Sketch of Brightlingsea Dolphins

## **Appendix A**

Photographs



Fig 1. – Dolphins



Fig 2 – Dolphin 1



Approximate High Tide Line

Fig 3 – Dolphin 2



Approximate High Tide Line

Fig 4 – Dolphin 3



Fig 5 & 6 – Results of hammer testing on Dolphin 1



Fig 7 - Typical condition of joints on Dolphin 1 above high tide line

#### Dolphin 2



Fig 8 - Upper section of Dolphin 2 (note extreme loss of section)



Fig 9 - Dolphin 2 above high tide line



Fig 10 - Dolphin 2



Fig 11 – Dolphin 2 below high tide line



Fig 12 – Dolphin 2



Fig 13 – Dolphin 2



Fig 14 – Dolphin 3



Fig 15 – Dolphin 3 above high tide line note deterioration of connections



Fig 16 – Dolphin 3 typical condition of hardwood timber rubbing rail



Fig 17 – Dolphin 3 at high tide line



Fig 18 – Dolphin 3 typical condition note hole in diagonal bracing member



Fig 19 – Dolphin 3 at high tide mark interior bracing



Fig 20 – Dolphin 3 typical condition of members at high tide line



Fig 21 – Dolphin 3 loss of section of timber rubbing rail and poor condition of connection bolt



Fig 22 – Dolphin 3 condition of member under marine growth



Fig 23 - Dolphin 3 above high tide line




Fig 24 - Dolphin 3 typical marine growth below tide line



Fig 25 - Dolphin 3 at mud line following removal of marine growth

## **Appendix B**

Correspondence with Brightlingsea Museum - Photos reproduced with kind permission



Brightlingsea 1953 – Dolphin structures circled



Brightlingsea 1995

## **Appendix C**



61257 – SK01: Sketch of Brightlingsea Dolphins



CONTRACT: *Brightlingsea Dolphins*  
ELEMENT: *Appendix B - SK01*

REF: *61257*  
SHEET:  
DATE:

*Yacht Club Quay*



*Dolphin 3 - Section A-A*

*1:5*

**N.B.**  
Steel Sections are historic and highly weathered sizes are approximate & compared to Dorman Section Tables



 **Colchester**  
01206 228800

 **London**  
020 7448 9910

 **Norwich**  
01603 230240

 **Cambridge**  
01223 314794

 **Bristol**  
01172 020070

[www.rj.uk.com](http://www.rj.uk.com)